



## Project Case Study

**Project:** Cactus Theater built 1938

**Location:** Lubbock, Texas

**Application:** Rainwater Collection

**System:** 15 Contain Rainwater Wall Tanks daisy chained together to create a rainwater collection / harvesting wall in two separate areas of the building.



**Contain Water Systems Inc.** Specializes in Rainwater Collection Tanks.

Seen in this project study is 15 Contain Rainwater Wall Harvesting Tanks setup in two banks and daisy chained together.

Water is collected from the gutters on the roof when it rains and stored in the tanks for irrigation and landscaping purposes.

This setup gives this customer a potential 930 usable gallons of rainwater in each rainfall eliminating cost and irrigation water otherwise used from the city.

### **Cactus Theater built 1938, Lubbock, Texas - Rainwater Collection System**

- 15 Contain Rainwater Wall Rainwater Harvesting Tanks
- 14 Contain Rainwater Wall Connection Couplers
- 2 Rain Harvest Leaf Catcher Filters supplied by Contain Water Systems
- 1 @ 1.5 inch Built in outlet hooked to pump and hose
- 1 @ 3" Overflow Kit



**Relationships...Strong as Steel**